

MAS_T_Repairpricelist (2022-06-01)

Article Nr.	Product	CHF	EUR
44530201	AAT 731-TG/12B	750	701
44530204	AAT 732-TG/16B	750	701
44730023	AIT 301-T/12B/I		
44730022	AIT 301-T/12B/U		
44730011	AIT 304-T/12B		
44730012	AIT 324-T/12B		
44120260	AIT 701-T	750	701
44120262	AIT 702-T	750	701
44120263	AIT 704-T	750	701
44530202	AIT 731-TG/12B	750	701
44530203	AIT 732-T/PTC	750	701
44530209	AIT 733-T/NTC	750	701
44530206	AIT 735-T/I/SIL	750	701
44730020	AOT 314-T/12B/I		
44730013	AOT 314-T/12B/U		
44120261	AOT 701-T	750	701
44120361	AOT 701-TH	750	701
44310202	BDG 831-TG	1000	935
44330001	CAN 831-T	1000	935
44540002	CDT 731-TG	1000	935
44130016	CPL 731-TG	1000	935
44120223	CPU 723-T	1000	935
44120265	CPU 725-LT	1000	935
44120365	CPU 725-LTH	1000	935
44120226	CPU 727-CT	1000	935
44120327	CPU 727-CTH	1000	935
44120330	CPU 727-DT	1000	935
44120227	CPU 727-T	1000	935
44120326	CPU 727-TH	1000	935
44510001	CPU 731-TG	1000	935
44510003	CPU 733-TG/EMD	1000	935
44510002	CPU 733-TG/ESD	1000	935
44510004	CPU 733-TG/OGF	1000	935
44310201	CPU 831-TG	1000	935
44390001	CPU 831-TG/S01	1000	935
44310203	CPU 832-TG	1000	935
44310207	CPU 833-TG	1000	935
44310209	CPU 833-TG/01	1000	935
44310204	CPU 835-T/SIL	1000	935
44310200	CPU 854-T	1000	935
44910001	CPU 941-TW	1000	935
44130021	CRS 731-TG	750	701
44670401	CTA 701S/DI-T	750	701
44170228	CTA 703-T	750	701
44720003	DDC 301-TF		
44720004	DDC 301-TH		
44120208	DDC 701-T	750	701

44120308	DDC 701-TH	750	701
44120210	DDC 712-T	750	701
44120310	DDC 712-TH	750	701
44520010	DDC 731-TG	750	701
44520011	DDC 731-TV	750	701
44520002	DDC 732-TG	750	701
44520003	DDC 735-TG/SIL	750	701
44520004	DDC 735-TV/SIL	750	701
44720001	DDE 301-TF		
44720002	DDE 301-TH		
44520008	DDE 731-TG	750	701
44520009	DDE 731-TV	750	701
44520006	DDE 735-TG/SIL	750	701
44520007	DDE 735-TV/SIL	750	701
44520013	DDM 731-TG/EMD	750	701
44520015	DDM 731-TV/EMD	750	701
44530103	DDT 731-TW/1A	750	701
44530104	DDT 732-TF/2A	750	701
44530108	DDT 732-TG/05A	750	701
44530109	DDT 735-TG/SIL	750	701
44530110	DDT 735-TV/SIL	750	701
44530214	DDT 737-TV/SIL	750	701
44530215	DDT 738-TF/SIL	750	701
44530213	DDT 738-TG/SIL	750	701
44730001	DIT 301-TF		
44730002	DIT 301-TH		
44730003	DIT 302-TF		
44730004	DIT 302-TH		
44730005	DIT 303-TF		
44730006	DIT 303-TH		
44730024	DIT 309-TF		
44730014	DIT 332-TF		
44730015	DIT 332-TH		
44730025	DIT 337-TF		
44730059	DIT 337-TH		
44120250	DIT 701-T	750	701
44120350	DIT 701-TH	750	701
44120255	DIT 701-TP	750	701
44530102	DIT 732-TW	750	701
44530105	DIT 733-TF	750	701
44530205	DIT 735-TG/SIL	750	701
44530207	DIT 735-TV/SIL	750	701
44730007	DOT 301-TF		
44730028	DOT 301-TF/2A/PS		
44730008	DOT 301-TH		
44730009	DOT 302-TF		
44730010	DOT 302-TH		
44730029	DOT 305-TF/2A/PS		
44730026	DOT 309-TF		
44730016	DOT 322-TF		
44730017	DOT 322-TH		
44730018	DOT 332-TF		

44730019	DOT 332-TH		
44730027	DOT 337-TF		
44730060	DOT 337-TH		
44120251	DOT 701-T	750	701
44120351	DOT 701-TH	750	701
44120252	DOT 702-T	750	701
44120254	DOT 703-T	750	701
44530208	DOT 732-TW	750	701
44530106	DOT 733-TR	750	701
44530107	DOT 733-TR/S01	750	701
44530211	DOT 736-TV/SIL	750	701
44530212	DOT 738-TF/SIL	750	701
44530210	DOT 738-TG/SIL	750	701
44130203	ECS 901-TW	1000	935
44130204	ECS 901-TW/PoE	1000	935
44130205	ECS 902-TW	1000	935
44130206	ECS 902-TW/PoE	1000	935
44130217	ECU 901-TW	1000	935
44130218	ERP 901-TW	1000	935
44130219	ERP 901-TW/IPS	1000	935
44130220	ERP 902-TW	1000	935
44130221	ERP 902-TW/IPS	1000	935
44130108	ERT 831-TG	1000	935
44130115	ERT 831-TO	1000	935
44130102	ESM 801-TG	1000	935
44130103	ESM 802-TG	1000	935
44130105	ESM 831-TG	1000	935
44130110	ESM 832-TF/PoE	1000	935
44130106	ESM 832-TG	1000	935
44130113	ESM 832-TO	1000	935
44130117	ESM 832-TO/PoE	1000	935
44130111	ESM 833-TF/PoE	1000	935
44130107	ESM 833-TG	1000	935
44130118	ESM 833-TO/PoE	1000	935
44130101	ESU 801-TG	1000	935
44130120	EWM 902-TW	1000	935
44130121	EWM 903-TW	1000	935
44130122	EWM 904-TW	1000	935
44950006	GCH 901-TW	1000	935
44950003	GCR 901-TW	1000	935
44950002	GMR 901-TW	1000	935
44130017	GWC 531-TF	1000	935
44950001	GWC 901-TW	1000	935
44950005	GWE 901-TW	1000	935
44130018	GWM 531-TF/EMD	1000	935
44130019	GWM 531-TF/ESD	1000	935
44950004	GWM 901-TW/EMD	1000	935
44750001	HMI 301-TW	1000	935
44150012	HMI 712-T	1000	935
44150517	HMI 8341-TM/01	1000	935
44150537	HMI 8352-TM	1000	935
44150544	HMI 8354-TM	1000	935

44150538	HMI 8362-TM	1000	935
44150550	HMI 8452-TW	1000	935
44150547	HMI 8452-TW/SIL	1000	935
44150551	HMI 8454-TW	1000	935
44150548	HMI 8454-TW/SIL	1000	935
44150552	HMI 8462-TW	1000	935
44150549	HMI 8462-TW/SIL	1000	935
44150013	MMIC 702-T	1000	935
44330003	MVB 831-T/EMD	1000	935
44330003.D	MVB 831-T/EMD Rev.D	1000	935
44330006	MVB 831-T/EMD/01	1000	935
44330004	MVB 831-T/ESD	1000	935
44330007	MVB 831-T/ESD/01	1000	935
44170046	NTC 701-T	750	701
44170045	NTC 701-TH	750	701
4311xxxx	PMC Serien	1000	935
44330002	PNI 831-T	1000	935
44770202	PSC 301-TF		
44770203	PSC 301-TH		
44570201	PSM 731-TM	750	701
44570200	PSM 731-TV	750	701
44570220	PSM 731-TW	750	701
44570203	PSM 732-TM	750	701
44570202	PSM 732-TV	750	701
44570225	PSM 732-TW	750	701
44570205	PSM 733-TW	750	701
44570224	PSM 734-TW	750	701
44570223	PSM 734-TW/S01	750	701
44370201	PSM 831-TM	750	701
44370200	PSM 831-TV	750	701
44570219	PSM 831-TW	750	701
44370204	PSM 833-TW	750	701
44570221	PSM 834-TW	750	701
44370202	PSM 835-TG	750	701
44370203	PSM 835-TV	750	701
44570222	PSM 835-TW	750	701
44570204	PST 731-TG	750	701
44120253	PWT 701-T	750	701
44540001	PWT 731-TG	750	701
44540003	PWT 732-TG	750	701
44570061	REN 704-TF/001	1000	935
44570062	REN 704-TF/SIL/001	1000	935
44730050	SAIT 302-T/12B/I		
44730051	SAIT 302-T/12B/U		
44730048	SAIT 304-T/12B/I		
44730049	SAIT 304-T/12B/U		
44740002	SBCC 301-TF		
44770024	SBTM 301-T		
44740003	SCIT 304-T		
44910002	SCPU 941-TW	1000	935
44720007	SDDE 301-TF		
44730030	SDIT 301-TF		

44730031	SDIT 302-TF		
44730032	SDIT 332-TF		
44730033	SDIT 342-TF		
44730034	SDOT 301-TF		
44730036	SDOT 302-TF		
44730037	SDOT 312-TF		
44730038	SDOT 322-TF		
44730039	SDOT 332-TF		
44770206	SPSC 301-TF		
44770205	SPSP 301-TF		
44740001	SWSP 301-TF		
44130015	TBC 702-T	1000	935
44130207	TBS 901-TW	1000	935
44130208	TBS 901-TW/PoE	1000	935
44130209	TBS 902-TW	1000	935
44130210	TBS 902-TW/PoE	1000	935
44130215	TDC 901-TW	1000	935
44130216	TDM 901-TW	1000	935

	Failure cannot be reproduced	500	467
	Unit cannot be repaired	500	467
	Repair not offered		
	Industrial products have the same price for the repair as the models listed (e.g. CPU 723 = CPU 723-T)		
	Other products that are not listed can be requested separately about the feasibility and price of the repair		